



AMPERITE CROSS REFERENCE GUIDE FOR P & B TDR'S

P&B Series	P&B Part Number	Function	Amperite Series	Amperite Part Number	Note	P&B Series	P&B Part Number	Function	Amperite Series	Amperite Part Number	Note
CB	CB-1001B-70	1	DC10	120AP .1-1SDC		CD	CDD-38-30003	1	DC10	24DP .1-10SDC	
CB	CB-1002B-70	1	DC10	120AP .1-6SDC	A	CD	CDD-38-30004	1	DC10	24DP .6-60SDC	
CB	CB-1003B-70	1	DC10	120AP .1-10SDC		CD	CDD-38-30005	1	DC10	24DP 1.8-180SDC	
CB	CB-1004B-70	1	DC10	120AP .6-60SDC		CD	CDD-38-30008	2	DCR10	24DP 1.8-180SDCR10	
CB	CB-1005B-70	1	DC10	120AP 1.8-180SDC		CD	CDD-38-30009	2	DCR10	24DP .1-1SDCR10	
CB	CB-1006B-70	1	DC10	120AP 1-10MDC		CD	CDD-38-30010	2	DCR10	24DP .1-6SDCR10	A
CB	CB-1007B-70	1	DC10	120AP 10-100MDC		CD	CDD-38-30011	2	DCR10	24DP .3-30SDCR10	
CB	CB-1008A-70	1	DC10	120AP 1SDC		CD	CDD-38-30012	2	DCR10	24DP .6-60SDCR10	
CB	CB-1009A-70	1	DC10	120AP 10SDC		CD	CDD-38-30014	2	DCR10	24DP .1-10SDCR10	
CB	CB-1010B-79	3	CI	120AP .1-1CI	B	CD	CDD-38-40002	1	DC10	48DP .6-60SDC	
CB	CB-1011B-79	3	CI	120AP .1-6CI	C	CD	CDD-38-40011	2	DCR10	48DP .1-10SDCR10	
CB	CB-1012F-70	1		Contact Factory		CD	CDD-38-40012	2	DCR10	48DP .6-60SDCR10	
CB	CB-1013F-70	1		Contact Factory		CD	CDD-38-60001	1	DC10	110DP .1-10SDC	
CB	CB-1014B-79	3	CI	120AP .1-10CI	B	CD	CDD-38-60002	1	DC10	110DP .6-60SDC	
CB	CB-1015B-79	5		Contact Factory		CD	CDD-38-60003	1	DC10	110DP 1.8-180SDC	
CB	CB-1016B-79	3	CI	120AP .6-60CI	B	CD	CDD-38-60004	1	DC10	110DP .1-1SDC	
CB	CB-1017B-79	3	CI	120AP 1.8-180CI	B	CD	CDF-38-70001	1		Contact Factory	
CB	CB-1018B-79	3		Contact Factory		CD	CDF-38-70002	1		Contact Factory	
CB	CB-1019A-79	3	CI	120AP 1CI	B	CD	CDF-38-70003	1		Contact Factory	
CB	CB -1020F-39	3		Contact Factory		CG	CGA-38-70005M	1	DC10	120AP300SDC	D
CB	CB-1021B-78	2		Contact Factory		CG	CGA-38-80005M	2		Contact Factory	
CB	CB-1022B-78	2		Contact Factory		CG	CGB-38-70005M	1	DC10	120AP5-300SDC	E
CB	CB-1023B-78	2		Contact Factory		CG	CGB-38-70010M	1	DC10	120AP1-10MDC	D
CB	CB-1024B-78	2		Contact Factory		CG	CGB-38-70010S	1	DC10	120AP1-10SDC	F
CB	CB-1025A-78	2		Contact Factory		CG	CGB-38-70050M	1	DC10	120AP1-60MDC	G
CB	CB-1026D-30	1	DC10	24DP .1-1SDC		CG	CGB-38-70050S	1	DC10	120AP6-60SDC	H
CB	CB-1027D-30	1	DC10	24DP .1-6SDC	A	CG	CGB-38-70100M	1	DC10	120AP10-100MDC	D
CB	CB-1028D-30	1	DC10	24DP .1-10SDC		CG	CGB-38-78005M	2		Contact Factory	
CB	CB-1029D-30	1	DC10	24DP .6-60SDC		CG	CGB-38-78005S	2		Contact Factory	
CB	CB-1030D-30	1	DC10	24DP 1.8-180SDC		CG	CGB-38-78010M	2		Contact Factory	
CB	CB-1031D-30	1	DC10	24DP 1-10MDC		CG	CGB-38-78050M	2		Contact Factory	
CB	CB-1032C-30	1	DC10	24DP 1SDC		CG	CGB-38-78050S	2		Contact Factory	
CB	CB-1033C-30	1	DC10	24DP 10SDC		CG	CGB-38-78100M	2		Contact Factory	
CB	CB-1034D-39	3	CI	24DP .1-6CI	C	CG	CGB-38-79005S	3	CI	120AP .1-6CI	I
CB	CB-1035D-39	3	CI	24DP .1-10CI	B	CG	CGB-38-79010M	3		Contact Factory	
CB	CB-1036D-39	3	CI	24DP 1.8-180CI	B	CG	CGB-38-79010S	3	CI	120AP .1-10CI	J
CB	CB-1037D-38	2		Contact Factory		CG	CGB-38-79050M	3		Contact Factory	
CB	CB-1038D-38	2		Contact Factory		CG	CGB-38-79050S	3	CI	120AP .1-60CI	K
CB	CB-1039D-38	2		Contact Factory		CG	CGB-38-79100M	3		Contact Factory	
CB	CB-1040B-30	1	DC10	24AP .1-6SDC	A	CG	CGB-38-80005M	1	DC10	240AP 5-300SDC	E
CB	CB-1041B-30	1	DC10	24AP .1-10SDC		CG	CGB-38-80005S	1	DC10	240AP .1-6SDC	L
CB	CB-1042B-30	1	DC10	24AP 1.8-180SDC		CG	CGD-38-20010M	1	DC10	12DP 1-10MDC	D
CB	CB-1043B-39	3	CI	24AP .1-10CI	B	CG	CGD-38-30010M	1	DC10	24DP 1-10MDC	D
CB	CB-1044B-39	3	CI	24AP 1.8-180CI	B	CG	CGD-38-30050M	1	DC10	24DP 1-60MDC	G
CB	CB-1045B-38	2		Contact Factory		CG	CGD-38-39010M	3		Contact Factory	
CB	CB-1046B-38	2		Contact Factory		CG	CGD-38-39050M	3		Contact Factory	
CB	CB-1047D-20	1	DC10	12DP .1-10SDC		CH	CHA-38-70001	1	DC10	120AP 10SDC	
CB	CB-1048D-40	1	DC10	48DP .1-10SDC		CH	CHB-38-30001	1	DC10	24AP .1-10SDC	M
CB	CB-1049D-60	1	DC10	110DP .1-10SDC		CH	CHB-38-30003	1	DC10	24AP 1.8-180SDC	R
CB	CB-1050B-80	1	DC10	240AP .1-10SDC		CH	CHB-38-30011	2		Contact Factory	
CD	CDA-38-70012	1	DC10	120AP 1SDC		CH	CHB-38-70001	1	DC10	120AP .1-10SDC	M
CD	CDA-38-70014	1	DC10	120AP 10SDC		CH	CHB-38-70002	1	DC10	120AP .6-60SDC	Q
CD	CDA-38-70016	1	DC10	120AP 60SDC		CH	CHB-38-70003	1	DC10	120AP 1.8-180SDC	R
CD	CDA-38-70025	2	DCR10	120AP 1SDCR10		CH	CHB-38-70011	2		Contact Factory	
CD	CDA-38-70026	2	DCR10	120AP 5SDCR10		CH	CHB-38-70012	2		Contact Factory	
CD	CDA-38-70028	2	DCR10	120AP 30SDCR10		CH	CHB-38-70013	2		Contact Factory	
CD	CDB-38-30001	1	DC10	24AP .1-10SDC		CH	CHB-38-70021	3	CI	120AP .1-10CI	N
CD	CDB-38-30002	1	DC10	24AP .6-60SDC		CH	CHB-38-70022	3	CI	120AP .1-60CI	O
CD	CDB-38-30003	1	DC10	24AP 1.8-180SDC		CH	CHB-38-70023	3	CI	120AP 1.8-180CI	P
CD	CDB-38-30004	1	DC10	24AP .1-1SDC		CH	CHB-38-80001	1	DC10	240AP .1-10SDC	M
CD	CDB-38-30011	2	DCR10	24AP .3-30SDCR10		CH	CHB-38-80002	1	DC10	240AP .6-60SDC	Q
CD	CDB-38-30014	2	DCR10	24AP .1-10SDCR10		CH	CHD-38-30001	1	DC10	24DP .1-10SDC	M
CD	CDB-38-70001	1	DC10	120AP .1-1SDC		CH	CHD-38-30002	1	DC10	24DP .6-60SDC	Q
CD	CDB-38-70002	1	DC10	120AP .1-6SDC	A	CH	CHD-38-30003	1	DC10	24DP 1.8-180SDC	R
CD	CDB-38-70003	1	DC10	120AP .1-10SDC		CH	CHD-38-30011	2		Contact Factory	
CD	CDB-38-70004	1	DC10	120AP .6-60SDC		CH	CHD-38-30013	2		Contact Factory	
CD	CDB-38-70005	1	DC10	120AP 1.8-180SDC		CH	CHD-38-30021	3	CI	24DP .1-10CI	N
CD	CDB-38-70006	1	DC10	120AP .3-30SDC		CH	CHF-38-70002	1		Contact Factory	
CD	CDB-38-70011	1	DC10	120AP 1.2-120SDC		CK	CKA-38-70010	1	DC10	120AP 10SDC	
CD	CDB-38-70012	2	DCR10	120AP .6-60SDCR10		CK	CKA-38-78180	2		Contact Factory	
CD	CDB-38-70014	2	DCR10	120AP .1-10SDCR10		CK	CKB-38-30010	1	DC10	24AP .1-10SDC	
CD	CDB-38-70015	2	DCR10	120AP 1.8-180SDCR10		CK	CKB-38-37010	4	DOD	24A .1-10SDOD	S
CD	CDB-38-70016	2	DCR10	120AP .1-1SDCR10		CK	CKB-38-37060	4	DOD	24A .6-60SDOD	S
CD	CDB-38-70091	2	DCR10	120AP .1-6SDCR10	A	CK	CKB-38-70010	1	DC10	120AP .1-10SDC	
CD	CDB-38-70092	2	DCR10	120AP .3-30SDCR10		CK	CKB-38-70060	1	DC10	120AP .6-60SDC	
CD	CDC-38-20026	2	DCR10	12DP180SDCR10		CK	CKB-38-70120	1	DC10	120AP 1.2-120SDC	
CD	CDD-38-20020	2	DCR10	12DP .1-1SDCR10		CK	CKB-38-70180	1	DC10	120AP 1.8-180SDC	



AMPERITE CROSS REFERENCE GUIDE FOR P & B TDR'S (Page 2)

P&B Series	P&B Part Number	Function	Amperite Series	Amperite Part Number	Note	P&B Series	P&B Part Number	Function	Amperite Series	Amperite Part Number	Note
CK	CKB-38-77010	4	DOD	120A .1-10SDOD	S	CU	CUA-41-30001	1	DC10	24AP1SLDC	T
CK	CKB-38-77060	4	DOD	120A .6-60SDOD	S	CU	CUA-41-30010	1	DC10	24AP10SLDC	T
CK	CKB-38-77120	4	DOD	120A 1.2-120SDOD	S	CU	CUA-41-70001	1	DC10	120AP1SLDC	T
CK	CKB-38-78010	2		Contact Factory		CU	CUA-41-70003	1	DC10	120AP3SLDC	T
CK	CKB-38-78060	2		Contact Factory		CU	CUA-41-70005	1	DC10	120AP5SLDC	T
CK	CKB-38-78180	2		Contact Factory		CU	CUA-41-70010	1	DC10	120AP10SLDC	T
CK	CKB-38-79010	3		Contact Factory		CU	CUA-41-70120	1	DC10	120AP120SLDC	T
CK	CKC-38-60060	1	DC10	110DP60SDC		CU	CUA-42-30005	1	DC10	24AP5SLDC	V
CK	CKD-38-20010	1	DC10	12DP .1-10SDC		CU	CUA-42-30010	1	DC10	24AP10SLDC	V
CK	CKD-38-60060	1	DC10	110DP .6-60SDC		CU	CUA-42-70003	1	DC10	120AP3SLDC	V
CK	CKF-38-70010	1		Contact Factory		CU	CUA-42-70005	1	DC10	120AP5SLDC	V
CK	CKF-38-78010	2		Contact Factory		CU	CUA-42-70010	1	DC10	120AP10SLDC	V
CK	CKF-38-79060	3		Contact Factory		CU	CUA-42-70030	1	DC10	120AP30SLDC	V
CK	CKH-38-30010	1		Contact Factory		CU	CUB-51-30010	1	DC10	24AP .1-10SLDC	W
CK	CKH-38-38010	2		Contact Factory		CU	CUB-51-70010	1	DC10	120AP .1-10SLDC	W
CL	CLA-41-70003	1	DC10	120AP3SLDC	T	CU	CUB-51-70030	1	DC10	120AP .3-30SLDC	X
CL	CLA-41-70005	1	DC10	120AP5SLDC	T	CU	CUB-51-70060	1	DC10	120AP .6-60SLDC	Y
CL	CLA-41-70010	1	DC10	120AP10SLDC	T	CU	CUB-51-70120	1	DC10	120AP 1.2-120SLDC	Z
CL	CLA-41-70030	1	DC10	120AP30SLDC	T	CU	CUC-41-30001	1	DC10	24DP1SLDC	T
CL	CLB-51-30010	1	DC10	24AP .1-10SLDC	T	CU	CUC-41-30030	1	DC10	24DP30SLDC	T
CL	CLB-51-30120	1	DC10	24AP 1.2-120SLDC	T	CU	CUC-42-30005	1	DC10	24DP5SLDC	V
CL	CLB-51-70001	1	DC10	120AP .1-1SLDC	T	CU	CUF-41-30010	1		Contact Factory	
CL	CLB-51-70010	1	DC10	120AP .1-10SLDC	T	CU	CUF-41-30030	1		Contact Factory	
CL	CLB-51-70030	1	DC10	120AP .3-30SLDC	T	CU	CUF-41-30120	1		Contact Factory	
CL	CLB-51-70060	1	DC10	120AP .6-60SLDC	T	CU	CUF-41-70010	1		Contact Factory	
CL	CLB-51-70120	1	DC10	120AP 1.2-120SLDC	T	CU	CUF-41-70030	1		Contact Factory	
CL	CLC-41-20010	1	DC10	12DP10SLDC	T	CU	CUF-41-70120	1		Contact Factory	
CL	CLC-41-30005	1	DC10	24DP5SLDC	T	CU	CUF-42-30010	1		Contact Factory	
CL	CLD-51-20010	1	DC10	12DP .1-10SLDC	T	CU	CUF-42-70010	1		Contact Factory	
CL	CLF-41-30010	1		Contact Factory		CU	CUF-42-70030	1		Contact Factory	
CL	CLF-41-70010	1		Contact Factory		CU	CUF-42-70120	1		Contact Factory	
CL	CLF-41-70060	1		Contact Factory		CU	CUH-41-30010	1		Contact Factory	
CL	CLF-42-70010	1		Contact Factory		CU	CUH-41-30060	1		Contact Factory	
CL	CLF-42-70120	1		Contact Factory		CU	CUH-41-30120	1		Contact Factory	
CL	CLH-41-20120	1		Contact Factory		CU	CUH-42-30010	1		Contact Factory	
CL	CLH-41-30010	1		Contact Factory		CU	CUH-41-30120	1		Contact Factory	
CL	CLH-45-30010	1		Contact Factory							
CR	CRB-48-30010	6	DFA	24AA/ADFA							
CR	CRB-48-30030	6	DFA	24AB/BDFA	U						
CR	CRB-48-30060	6	DFA	24AC/CDFA							
CR	CRB-48-30120	6	DFA	24AD/DDFA							
CR	CRB-48-30180	6	DFA	24AE/EDFA							
CR	CRB-48-70010	6	DFA	120AA/ADFA							
CR	CRB-48-70030	6	DFA	120AB/BDFA	U						
CR	CRB-48-70060	6	DFA	120AC/CDFA							
CR	CRB-48-70120	6	DFA	120AD/DDFA							
CR	CRB-48-70180	6	DFA	120AE/EDFA							
CR	CRD-48-20010	6	DFA	12DA/ADFA							
CR	CRD-48-20030	6	DFA	12DB/BDFA	U						
CR	CRD-48-20060	6	DFA	12DC/CDFA							
CR	CRD-48-20120	6	DFA	12DD/DDFA							
CR	CRD-48-20180	6	DFA	12DE/EDFA							
CR	CRD-48-30010	6	DFA	24DA/ADFA							
CR	CRD-48-30030	6	DFA	24DB/BDFA	U						
CR	CRD-48-30060	6	DFA	24DC/CDFA							
CR	CRD-48-30120	6	DFA	24DD/DDFA							
CR	CRD-48-30180	6	DFA	24DE/EDFA							
CR	CRD-48-40010	6	DFA	48DA/ADFA							
CR	CRD-48-40030	6	DFA	48DB/BDFA	U						
CR	CRD-48-40060	6	DFA	48DC/CDFA							
CR	CRD-48-40120	6	DFA	48DD/DDFA							
CR	CRD-48-40180	6	DFA	48DE/EDFA							
CR	CRD-48-60010	6	DFA	110DA/ADFA							
CR	CRD-48-60030	6	DFA	110DB/BDFA	U						
CR	CRD-48-60060	6	DFA	110DC/CDFA							
CR	CRD-48-60120	6	DFA	110DD/DDFA							
CR	CRD-48-60180	6	DFA	110DE/EDFA							

FUNCTIONS:

- 1 = Delay On Operate
- 2 = Delay On Release
- 3 = Interval-On
- 4 = Delay On Drop-Out
- 5 = Triggered Interval-On
- 6 = Recycle Timer

NOTES:

- A = Timing is .1-6 Sec. Not .1-5 sec.
- B = Amperite units are analog not CMOS
- C = Timing is .1-6 sec. not .1-5 sec., Units are Analog not CMOS
- D = Repeatability is 1% not .05%
- E = Timing is 5-300 sec. not 30-300 sec., Repeatability is 1% not .05%
- F = Timing is .1-10 sec. not 1-10 sec., Repeatability is 1% not .05%
- G = Timing is 1-60 min. not 5-50 min., Repeatability is 1% not .05%
- H = Timing is .6-60 sec. not 5-50 sec., Repeatability is 1% not .05%
- I = Repeatability is 5% not .05%, Analog not CMOS, Timing is .1-6 sec. not .5-5 sec.
- J = Repeatability is 5% not .05%, Analog not CMOS, Timing is .1-10 sec. not 1-10 sec.
- K = Repeatability is 5% not .05%, Analog not CMOS, Timing is .1-60 sec. not 5-50 sec.
- L = Timing is .1-6 sec. not .5-5 sec., Repeatability is 1% not .05%
- M = Timing is .1-10 sec. not 1-10 sec.
- N = Timing is .1-10 sec. not 1-10 sec., Analog not CMOS
- O = Timing is .1-60 sec. not 1-60 sec., Analog not CMOS
- P = Timing is 1.8-180 sec. not 1-180 sec., Analog not CMOS
- Q = Timing is .6-60 sec. not 1-60 sec.
- R = Timing is 1.8-180 sec. not 1-180 sec.
- S = Units are 4 amp not 10 amp, Analog not CMOS
- T = Larger Header and Case
- U = Timing is .25-25 sec. not .3-30 sec
- V = Larger Header and Case & No Bracket
- W = Larger Header and Case, Timing is .1-10 sec. not 1-10 sec.
- X = Larger Header and Case, Timing is .3-30 sec. not 1-30 sec.
- Y = Larger Header and Case, Timing is .6-60 sec. not 1-60 sec.
- Z = Larger Header and Case, Timing is 1.2-120 sec. not 1-120 sec.